# Maryland Historical Trust

Maryland Inventory of Historic Properties number: 6 - U -	-A-179				
Maryland Inventory of Historic Properties number: 6-U-Name: 45219 over you work	rerex Evier.				
The bridge referenced herein was inventoried by the Maryland State Highway Administration as part of the Historic Bridge Inventory, and SHA provided the Trust with eligibility determinations in February 2001.					
The Trust accepted the Historic Bridge Inventory on April 3, 2001. The bridge received the following determination of eligibility.					
MARYLAND HISTORICAL TRUST  Eligibility Recommended Eligibility Not Recommended X					
Criteria:ABCD Considerations:A	A B C D E F G None				
Comments:					
Comments:  Reviewer, OPS:_Anne E. Bruder	Date:3 April 2001				

Maryland Inventory of Historic Properties Historic Bridge Inventory Maryland State Highway Administration Maryland Historical Trust

Maryland State Highway Administration  Maryland Historical Trust
SHA Bridge No. 11024 Name: US 219 over Youghiogheny River
Location: Street/Road Name and Number: US 219 (Elkins Oakland Road)
City/Town: Redhouse Vicinity X
County: Garrett
Ownership: X State County Municipal Other
This bridge projects over:RoadRailway_X_WaterLand
Is the bridge located within a designated district: _yes X no
_NR listed district_NR determined eligible district _locally designated_other Name of District
Bridge Type:
Timber BridgeBeam BridgeTruss-CoveredTrestleTimber-and-Concrete
_Stone Arch
_Metal Truss
_Movable BridgeSwingBascule Single Leaf_Bascule Multiple LeafVertical Lift_Retractile_Pontoon
Metal GirderRolled Girder Concrete EncasedPlate GirderPlate Girder Concrete Encased
_Metal Suspension
_Metal Arch
_Metal Cantilever
X Concrete Arch Concrete Slab Concrete Beam Rigid Frame
Other Tyne Name

#### **Describe Setting:**

Bridge 11024 carries US 219 over the Youghiogheny River in Garrett County. US 219 runs northeast and southwest over the northern flowing Youghiogheny River. The bridge is in a sparsely populated rural farming region. The bridge is surrounded by farmland.

#### **Describe Superstructure and Substructure:**

Bridge 11024 is a single-span filled concrete arch bridge. The length of the bridge is 27 feet with a clear span of 23 feet. The bridge has a rise of 8 feet from springline to the crown. The spandrel walls are approximately 5 feet high and 7 feet wide. There is a clear roadway width of 24 feet, with an overall bridge width of 26 feet 6 inches. The spandrel walls have been repaired and are failing. According to a 1995 inspection report the eastern spandrel wall has severe spalling and deterioration. There is a 12-foot by 2-foot by 2-foot section missing from the eastern walls. Fill on this side of the bridge near the arch ring is loose with up to a 2-foot opening near the apex of the ring. The west side wall has medium areas of heavy scaling and deterioration. Small spalls exist in the spandrel walls and the arch ring. The west side of the arch is in good condition. The overall condition of the bridge is fair, with a sufficiency rating of 48.3.

Bridge 11024 does not retain its original parapets. The bridge has concrete curbs with modified traffic barriers or guardrails. The guardrails are attached to steel posts. The steel posts are attached to a concrete cap that extends across the bridge.

## Discuss Major Alterations:

In 1927 the original bridge was widened. At an unknown date the 1927 parapet walls were removed and replaced with a guardrail system. The upstream spandrel wall has been repaired with gunite.

When Built: Unknown/1927

Why Built: Unknown

Who Built: State Roads Commission Who Designed: State Roads Commission

Why Altered: Parapets were unsafe and deteriorated.

Was this bridge built as part of an organized bridge building campaign? It is unknown why the original

bridge was built.

#### Surveyor Analysis:

This bridge may have NR significance for association with: Person

**A Events** 

\_\_C Engineering/Architectural

This bridge does not have National Register significance due to its poor condition and loss of parapets.

## Was this bridge constructed in response to significant events in Maryland or local history?

It is unknown why the first bridge at this site was built. However, during the early days of improved road construction in Maryland, a policy of building narrow roads and bridges was adopted so that a complete system of highways might be obtained in a reasonable time and with the limits of available funds. As the traffic increased it became necessary to reconstruct existing roads to sufficient width and strength. In 1918, the State Roads Commission developed the use of a concrete shoulder for widening and strengthening old roads of all types. By the end of 1930 Maryland had approximately 700 miles of roadway which had been widened and strengthened by the construction of concrete shoulders. With the widening of roadways many bridges were also widened.

Is the bridge located in an area that may be eligible for historic designation and would the bridge add to or detract from historic and visual character of the possible district?

No, this bridge is not located in an area that is eligible for historic designation.

# Is the bridge a significant example of its type?

No, this bridge is not a significant example of its type. The parapets have been removed. The spandrel walls are deteriorated and can not be repaired any further. The incisions on the spandrel walls and wingwalls that should be found on a structure rebuilt in 1927 are not present.

Does the bridge retain integrity of the important elements described in the Context Addendum?

No this bridge does not retain integrity of its character defining elements. The obvious loss is the bridge's parapets. The spandrel walls and the arch ring are deteriorated and losing fill.

Should this bridge be given further study before significance analysis is made and why?

No, the bridge should not be given further study.


Organization/Address\_

Phone number(410) 296-1635

Bibliography:				
	nty inspection/bridge files SHA inser (list):	SHA inspection/bridge files X		
Johnson 1899	son, Arthur Newhall  The Present Condition of Maryland Highways. In Report Geological Survey, The Johns Hopkins University Press,		Maryland. Maryland	
P.A.C. 1995	C. Spero & Company and Louis Berger & Associates Historic Highway Bridges in Maryland: 1631-1960: Highway Administration, Maryland State Department of			
State R 1958	Roads Commission  A History of Road Building in Maryland. State Road Maryland.	ads Commission of M	Maryland, Baltimore,	
Tyrrell,	ell, H. Grattan			
1909		Highways. The Myron	C. Clark Publishing	
SURVI	VEYOR:			
Date bi	bridge recordedDecember 1997			
	e of surveyor Wallace, Montgomery & Associates / P.A.C.	Spero & Company		

P.A.C. Spero & Co., 40 W. Chesapeake Avenue, Baltimore, MD 21204

**FAX number** (410) 296-1670





OVER 11011 G-V-A-179

OVER 11016 HENLY RIVER

CAREET CO Nd

DAV D KINI
1/9/95

SHA

NORTH APPROACH

101 -1



OVER MOVEHIOGHERLY LIVER

CAPPET CO MI

LAVIE KING

19195

5HA

SOUTH APPROACH

2014



CVER MOUGHINGHENN ZIVER

CARRETTON MI

LAVIN LINIT

11 JAK

544

WEST ELEVATION (DOWNSTREAM)

30-4



ER# 10/13/1024 G-V-A-179 OVER YOUGHIOGHENN RIVER GARRETI DU MO JAVIZ KING 1/19/95 SHA EAST ELEVATION (UTSIREAM)

4 4